

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-12581INITIAL
FES

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/08/94

04/11/94

RW 11-73

6597440

700

270 WIN

BDL

ACCESSORIES

W/STUDS

FROM:

FARMU, ROBERT
P O BOX 118
MILLERTON

PA 16936

SHIP TO:

FARMU, ROBERT
P O BOX 118
MILLERTONPA
16936

CUST NO: 095666 CLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER NC

059015

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

discharged when closed bolt

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Mfg. 11-73. Unable to duplicate customer concern as recd. Took trigger
assy. apart, still no fault found. Exchange trigger assy at no
charge as a gesture of good will and to restore customer
confidence in rifle.

PARTS

Trigger Assy Complete

COMMENTS

Trigger pull measured 4 1/4 to 5 LB
as rec'd. was left was 1006
Ran on RFL and removed
Outside of trigger assy exceptionally dirty

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS02561

Dear Sir:

This firearm discharged
one time when I closed
the bolt

Please advise me

Robert Faumu

P.O. Box 118

Millerton, Pa

16936-0118

Customer concern in need. Took trigger
group. Exchange trigger Assy at 100
and will and to return customer

COMMENTS

Trigger pull measured 4 1/4 to 6 LBS
as spec'd. was left was 1006

Rust on bolt and receiver
Outside of trigger Assy exceptionally dirty

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB.		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 1/94

OFFICE COPY