

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
ServiceORDER
R 95-04579INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED

01/24/95

DATE OPENED

02/06/95

DATE CODE

KW 5-72

SERIAL NUMBER

6559020

NEW SERIAL NUMBER

MODEL AND GRADE

700 270

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

GRIGAR, DAN
10 SANDY CREEK
BRENNHAM

TX 77833

SHIP TO:

GRIGAR, DAN
10 SANDY CREEK
BRENNHAMTX
77833

CUST NO: 114487 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

3-22-95

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Unable to duplicate customer concern as rec'd. Trigger felt sluggish and was slow to return. Took trigger disy apart, both sepi and trigger were gummed up with solidified oil and trigger adjusting screws (all 3) were adjusted outside of the factory - not recommended. Exchange trig. assy at a special price strictly as a gesture of good will.

PARTS

COMMENTS

Trig. pull measured 4 3/4 to 5 as rec'd. New lift ans. .007

Just take down new hose as rec'd.

See gunner manual for proper care and maintenance

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

L

OFFICE COPY

RD6925 RB

PS02741