

File Number:	18847		Arms Service number:	63652	
Last Name:	GUNWORKS OF COLORADO, INC		First Name:		
Street:	3355 SOUTH YARROW STREET #E-113		City:	LAKEWOOD	
State:	CO	Zip:	80227	Home Ph:	
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1040	
Concern:	OTHER- UNSPECIFIED OR UNDETERMINED				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SANITA	Classification:	UNC	UNJ UNC UND J	
Settlement Detail:	REPLACE TRIG ASSEM AT N/C		Settlement Amount:	\$65.00	
Date Opened Rem:	4/1/2003	Date Opened by P/S:	4/1/2003	Caliber:	
Date of Incident:		Date Closed:	4/2/2003	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	A6418999	Date Code:	AO
RAMAC:	700			Date Mfgd:	3/1/1977
Custody:		Litigation:	☐	PreLitigation:	☐
		Obsolete:	☐		
Time of Modification:	7:26:51 AM	Comments:	small metal chip found inside the trigger pin hole of the trigger Repair and shipping documents 4/24/03.		
Date of Modification:	4/2/2003				