


Serial Number: C6273420

Model ID: 700



RE00002694

35 Wkdam

1/18/00

Would not fire
then fired on bolt change

Upon receipt we could not duplicate
the reported concern

Exam. revealed that the action
& inside the trigger assembly covered with a
heavy sticky substance.

Ref not cleaned properly

Replace complete trigger assembly at 50% of cost
Clean action. GO ahead

1027
4015