


Sunday
May 15, 1994

Setup file

Remington Arms Co., Inc
Ilion, New York 13357



To Whom It May concern:

In 1985 I purchased a Remington Model 700 ADL 270 caliber fine
arm, serial # B-6559630.

I have had problems with safety and misfiring since the seventh
shot was fired. The gun goes off by itself; does not fire when
trigger is pulled when safety is on fire; fires when trigger is
pulled when on safe. There are times the safety cannot be moved
at all. In my opinion this gun is totally unsafe and a piece of
junk.

It has been sent to you twice with no repair results. Before
someone gets hurt, I would like a solution to this problem on
a new gun.

If you have any questions you may call me at my home number.....
(610) 282-3891. I hope to hear from you very soon with a satis-
factory reply or I will have my lawyer contact you.

*Left message on answering machine
1:40 PM 5/19/94*

Thank you,

Hugo L. Gelsebach

Hugo L. Gelsebach
740 Povenski Rd.

Quakertown, Pa. 18951-1812

*5/19/94 Called customer left message to return my call -
message to call collect. HJ*