

File Number:	21704		Arms Service number:	102573	
Last Name:	GLOUCESTER CO PROSECUTOR		First Name:	JOE	
Street:	PO BOX 623		City:	WOODBURY	
State:	NJ	Zip:	08096	Home Ph:	
Work Ph:	856-491-6026	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4040	Cause:	OTHER - NON-REMINGTON TA		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	REPAIR AT SPECIAL PRICE		Settlement Amount:	\$0.00	
Date Opened Rem:	10/21/2005	Date Opened by P/S:	10/24/2005	Caliber:	308
Date of Incident:		Date Closed:	10/25/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	C6800569	Date Code:	ON
RAMAC:	700	Date Mfgd:	7/23/1993	Litigation:	<input type="checkbox"/>
Custody:		PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>
Time of Modification:	12:43:16 PM				
Date of Modification:	11/1/2005				
Comments:	Claims firing on bolt closing - trigger assembly in firearm is not of Remington manufacture. Quote installing Remington TA and cleaning action at 1/2 normal charges.				