

Remington.



REMINGTON ARMS COMPANY, Inc.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS

ILION, NEW YORK 13357

PAGE 1

DATE: 12/27/91

PARTS: (315)895-7493, REPAIRS: (315)895-7791

SOLD TO:

SHIPPED TO

REPAIR ORDER NO.

REPAIR ORDER NO.: 91-26064

91-26064

HOLM, OTIS C
824 10TH AVE N E
BRAMERD

MN 56401

CUSTOMER NUMBER: 54726

HOLM, OTIS C
824 10TH AVE N E
BRAMERD

811

56401

THIS IS AN ESTIMATE TO REPAIR, RECONDITION OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW. RETURN THE FIRST COPY TO REMINGTON ARMS CO. INC. ILION, NY 13357. KEEP THE SECOND COPY AS YOUR RECEIPT.

REPAIR TO TAKE ABOUT 4 WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN THIRTY DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED.

700 6MM REM VAR SERIAL NUMBER: A6705817

L/ WOOD

L/ REAR SIGHT

WOG 1 OF 2

CUSTOMER REQUEST:

GUN FIRED WHEN CLOSING BOLT & when you Take SASe oSS.

MAIN FAULT FOUND:

UNABLE TO DUPLICATE COMPLAINT. TRIGGER ASSM. AND SAFETY WORK PROPERLY. RIFLE OPERATES NORMALLY IN EVERY RESPECT. TRIGGER PULL 4 & 1/4 POUNDS, SEAR-LIFT. 0085"
DATE OF MFG: 12-78

1. 0026345 TRIGGER ASSEM RM
TEST - USING SLAVE STOCK
RBSZMAR

28.

TOTAL REPAIR CHARGE 28.
TAXES 1.

INSURANCE
PARCEL POST 5.

TOTAL CHARGES 35.

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

OMER COPY