

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 74-36501INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
12/12/94DATE OPENED
12/17/94DATE CODE
EY 10-74SERIAL NUMBER
6797858

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL

ACCESSORIES W/STUDS L/SIGHTS

FROM:

HICKEY, TOM ED
RT 4 BOX 338A
ROCKWOOD

TN 37854

SHIP TO:

HICKEY, TOM ED
RT 4 BOX 338A
ROCKWOODTN
37854

CUST NO: 110716 C.O.D.L

ACCOUNT NUMBER
063103

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA
UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

1/20
Product Support
Technical cleaning test

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

28⁰⁰

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Failed to fire then fired when closing bolt on next round

MAIN FAULT

*Major 10/74 Trigger, very slow to return as rec'd. (sluggish)
Took trigger apart, found sides of trigger and trigger housing
covered with gummy (solidified) oil. Trigger likely stuck in
pulled condition as well as seen on first shot then the
sear went down when bolt was closed again. Exchange
Trig Assy. at a spec. price as a gesture of good will.*

PARTS

Trig Assy.

COMMENTS

*Trigger pull measured 4 1/2 to 5 lbs
as rec'd. sear set was .0065
Some rust on firing pin
sear was gummy*

*See owners manual for proper
cleaning and maintenance*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS03057