

RECEIVING AND ESTIMATING REPORT

INITIAL FPS		CUSTOMER ORDER NO.		COMMENTS	
DATE RECEIVED 01/02/91	DATE OPENED 01/09/91	DATE CODE DE 7-84	SERIAL NUMBER B6624581	MODEL AND GRADE 700 270 WIN BDL	ORDER R 91-00734
ACCESSORIES W/STUDS		SCOPE BASE			

FROM:

HENRY'S GUNS "R" US
RT 11 N MAIN ST
RT 1 BOX 442
MT JACKSON

VA 22842

SHIP TO:

HENRY'S GUNS "R" US
RT 11 N MAIN ST
RT 1 BOX 442
MT JACKSON

VA 22842

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Trigger runs right with fire when bolt closes and also when trigger is pulled a heavy hammer before gun fires.

MAIN FAULT

Trigger has been completely mis-adjusted outside of factory - malant missing from all adjustment screws. 1) insufficient over travel 2) insufficient rear engagement of trigger pull out of gear at 6.5 pounds. Trigger and hammer will sometimes not separate in cocking because of incorrect over-travel.

PARTS

Send quotation for new trigger assembly & hammer rod, as good - will gesture.

REPAIRMAN R.E.W.	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

STICK!

RD6925 REV. 7/90

PS03103