

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-07686INITIAL
FDCCUSTOMER ORDER NO.
FB692DATE RECEIVED
02/23/94DATE OPENED
03/02/94

DATE CODE

SERIAL NUMBER
A6640750

NEW SERIAL NUMBER

MODEL AND GRADE
700 270

WIN. BDL

ACCESSORIES
W/STUDS

FROM:

HOMESTEAD ACE HARDWARE
HWY 78 N
DYERSBURG

TN 38024

SHIP TO:

HOMESTEAD ACE HARDWARE
HWY 78 N
DYERSBURGTN
38024

CUST NO:006358 ILIONL

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Product Service

REPAIR CHARGE 25.
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1		
REC. ASSY.		B5		D2	E4	F4
WOOD				D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, unable to duplicate customer concern of firing on bolt
spring. Found no malfunctions with safety assembly. However, examination of
trigger assembly housing & action revealed a heavy ground up, rollers on all

PARTS

The bolt stop roller will no return

COMMENTS

Replace complete trigger assembly
Clean action at 1/2 normal upstroke
Part, as picture of part will
go ahead

REPAIRMAN

CC

PROOF

CLEAN

TEST

TARGET

PATTE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1

PS03187