

3/22/94 -

Rem Arms Co Inc
Ilion N.Y.

Dear Quality Control

Re 700 Rifle

Based on "60 Minutes" report on 3/20/94
I suspect I (may) own a Remington
Bolt action 700 series rifle that is
subject to "ticking" or accidental?
Discharge (firing without using the trigger).

I understand @ 1% of all 1975 and
prior Remington rifles are subject to
malfunction... I experienced such a
malfunction (I think) in the early 1970's
when rifle fired through the wall of the
house when bolt was closed.

I have a Remington 700 series bolt
action rifle (308 WIN) # 234770
PAT NO 2,473,373, 2,514,981 purchased
sometime in the early 1970's.

Please research and advise me if
the rifle is one that is subject to mal-
function and if so what is the next
step. Thanks

Sincerely,
L. Halton Jr.

C. -File

453-4765

Leonard C Halton Jr
Rt 2 Box 4380
Bristol VT 05443

(802) 453-3374