

Date: 2/27/04

By: Smith

**FIREARM INSPECTION WORKSHEET**

**BACKGROUND**

Customer name: Robert Hayden

R.E. Number: 77654

Reason for inspection: Pistol discharged 3 times

**FIREARM**

Manufacturer: S&W Model: 700

Serial Number: 6893716 Date of Manufacture: 10/75

Overall external condition: Fair

Barrel condition: \_\_\_\_\_

Receiver condition: \_\_\_\_\_

Stock condition: \_\_\_\_\_

Bolt/firing pin condition: \_\_\_\_\_

Trigger assembly condition: \_\_\_\_\_

Engagement: \_\_\_\_\_

Adjustments/alterations: \_\_\_\_\_

Other: For Maintenance trigger group covered with

Headspace: string substance

Function evaluation: \_\_\_\_\_

Feeding: \_\_\_\_\_

Extraction/ejection: \_\_\_\_\_

Trigger pull: 4 1/2 lbs

Manual safety: \_\_\_\_\_

Test firing results (if applicable): \_\_\_\_\_

DISPOSITION

Replace trigger assembly at 500 ft

ADDITIONAL COMMENTS

Could not duplicate the reported  
condition