JANUSZEW SK 354 ST. HWY - -ECENVED JACKSON MO 63755 1 1 7 1994 CALL DOOL PRODUCT SERVICE

October 30, 1994

Remington Arms Company, Inc Arms Service Division Ilion, New York 13357

Gentlemen:

.

I recently learned of the safety release problem on the Remington #700. I have experienced the gun firing when the safety was released only once.

My question, is there a local representative in my area of Cape Girardeau, Missouri to whom I can rectify this problem. I own a Remington #700 in a 308 caliber - serial #6312514.

Thank you,

Steven A. Januszewski 354 State Highway Y Jackson, MO 63755

Phone after 6 PM 314 243-6067

