

RECEIVING AND ESTIMATING REPORT

COMMENTS

Att product
serviceORDER
R 98-16272

INITIAL

CUSTOMER ORDER NO.

JJM

W/MAG BOX, SCREWS, TRIGGER GUARD

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ADL

08/12/98

08/13/98

EC 10-82

B6417395

700

7MM MAG

ACCESSORIES

SCOPE BASE

L/SIGHTS

L/FOLLOWER

L/MAG SPRING

FROM:

SHIP TO:

JACKSON, MARK E
273 RADA AVE
WESTON

WV 26452

JACKSON, MARK E
273 RADA AVE
WESTON

WV

26452

CUST NO: 191079 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

2293001

8/18/98

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

28.00

8.00

36.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.					E4	F4
WOOD			C1	D3	E5	F5
METAL						
MAIN FAULT						

Something when flipping off the sight will fire
Also when looking down on a bullseye

Upon receipt we could not duplicate the reported concerns,
but did find during our exam. that the inside of the trigger housing
all internal parts & the action are covered with a heavy brown
slimy substance. Rifle has been properly maintained.

#26345

Go ahead

Replace the complete trigger assembly
& clean the action at 1/2 the normal
recommended

PROOF	CLEAN	TEST	TARGET	PATTERN
FB	✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/97

PS03430