

RECEIVING AND ESTIMATING REPORT

R93-09752

CUSTOMER ORDER NO. L46055					
RECEIVED 12/93	DATE OPENED 04/13/93	DATE CODE	SERIAL NUMBER A6663447	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG BDL/LH
SSORIES W/STUDS		SCOPE BASE		L/SIGHTS	

SHIP TO:	
JAY'S SPORTS N 88 W 15263 MAIN ST MENOMONEE FALLS WI 53051	JAY'S SPORTS N 88 W 15263 MAIN ST MENOMONEE FALLS WI 53051

QUANTITY	ACCOUNT NUMBER N/C	CUST NO:007266 ILION	PROM. DATE	ESTIMATED	VIA UPS
CONDITION					REPAIR CHARGE EXCISE 85.00 TAX INSURANCE UPS PARCEL POST TOTAL

TOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	B1				"
GER GROUP		B2				F1
ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
AL			C2			

Upon receipt of rifle, ammunition revealed fingerprint of trigger to have been heavily bent down and damaged. The end of the trigger broke the inside of the trigger guard down. All parts removed. Replacement on how tight the guard comes on, the trigger follows down. No other safety is there. (Jim Hutton ammunition, note attached)

Replace trigger assembly, complete at 12 normal replacement cost.

Go ahead - OK per JPH 4/25/94

REPAIRMAN BEA	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8925 REV. 1/92

PS03490