

Remington.**14467****Factory Repair Instructions**

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: Model Seven Youth	Serial Number: 7730698	
Name: Joseph Kawaky	Date of Purchase: 8/16/97	
Address: 240 Reuben Johnson Rd. ←(shipping)		
P.O. Box 65169 ←(mail)		
City: Port Ludlow	State: WA	Zip: 98365
Phone (Daytime): 360/437-9550	Fax: 360/437-9582 (work)	
E-mail Address: kawaky@tscnet.com		
I would like to receive future e-mail updates from Remington. <u>NO</u>		

Please describe your problem: This gun is a significant safety hazard and potentially a huge liability for Remington. The safety does not work like a safety - it works like a trigger! Chamber a load, lock the bolt, and when you move the safety from "S" to "F" the gun discharges without ever touching the trigger. Huge risk!

Additional Information: (Ammo type, brand, handload specifications, etc.)

This weapon has had only 12 total rounds of ammo fired in its entire life. I used Federal Classic .243W factory loads.

Ship your INSURED firearm by either UPS or Parcel Post to:

Remington Arms Co., Inc.
Attn: Arms Service Division
14 Hoefler Avenue
Ilion, NY 13357

I'm very concerned now whether this gun is safe to give to my young son for deer hunting next month. Please advise re: the cause and your fix.

⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

:: Record the serial number of your firearm before sending it to us.
or damage in shipping and handling. Preferably,

ent loss or damage.
during shipment, so you may elect to purchase

*Change 230145
Trigger housing rusty from unknown
source - Replace Trigger housing at NO
charge*

Thankyou
a longtime
customer,
Be Kawaky

7730698**Model: 7****RE00014467**

10/00 4:24 PM