

Date: 6/15/04

By: Bruce Travis Sn.

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Don Krohn

R.E. Number: 81911

Reason for inspection: Fails to fire - Fired when trigger pulled
AND safe released

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: E6286283 Date of Manufacture: 4/96

Overall external condition: GOOD

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: —

Headspace: —

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 5 1/2 #

Manual safety: O/CAY

Test firing results (if applicable): —

DISPOSITION

Trig. + inside trig. plate rusty preventing proper
return of trig. - Replace complete FPA, clean action
properly lube, Function test @ 1/2 msp
ADDITIONAL COMMENTS