March 30, 1994

From: Kenneth Kitsch

115 Sharon Drive

Douglassville, PA 19518

Re: Model 700, A6378214, 6mm

History:

- Gun was purchased (used) from Ship's Sporting Goods, Blossburg, PA (John Shipulefski prop) between 1981 - 1985.

- On first hunting trip while releasing safety in order to unload, gun discharged.
- I then took it to a range the same day and fired an entire box of rounds in an effort to duplicate the malfunction -- this was unsuccessful.
- When I arrived home, I demonstrated the failure to my wife and gun discharged (it was not loaded at this time).
- I called a gunsmith and described the problem -- he said that someone had probably adjusted the trigger and that this could not be done on a Model 700. I took the gun to him -- he returned it repaired and charged me either \$10 or \$12.
- I have not fired the rifle since then. I heard the 60 min. spot and called your Customer Service Dept. -- they said send it in!

I doubt the gun is safe. Please advise.

Kenneth Kitsot elk

Kenneth Kitsch

10