

RECEIVING AND ESTIMATING REPORT

COMMENTS

Set up FILE
CALL TAG ATTN: TOM NAGLEORDER
R 94-13995
K

INITIAL FPS	CUSTOMER ORDER NO.				
DATE RECEIVED 04/22/94	DATE OPENED 04/22/94	DATE CODE LZ 2-75	SERIAL NUMBER 6817037	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 ADL
ACCESSORIES W/STUDS		SCOPE BASE			

FROM:

KRIDLER, BRADLEY P.
HCR 61 BOX 121
SUMERDUCK

VA 22742

SHIP TO:

KRIDLER, BRADLEY P.
HCR 61 BOX 121
SUMERDUCKVA
22742

CUST NO: 096434 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C <i>059015</i>	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION					REPAIR CHARGE
☐ NEW					EXCISE
☒ LIGHTLY WORN					TAX
☐ WORN					INSURANCE
☐ VERY WORN					UPS
☐ UNREPAIRABLE					PARCEL POST
☒ MARRED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E1	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Mfgn 2/75 Unable to duplicate customers concern as received. Tried two days in a row and trigger functioned normally in every respect. ON DISASSEMBLY some rust was found on Bolt stop, Trigger connector, both sides of trigger and trigger side plates. Exchange trigger Assy at N/C as gesture of good will and to restore customers confidence in Rifle.*

PARTS	COMMENTS <i>Trigger pull measured 4 LBS as Rec. and seal lift measured .010</i>					
	REPAIRMAN <i>WLB</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS03684