

21 November 2005

Dan Klessig 5508 Boot Leg Road Eagle River, WI 54521

RE: / Model 700 Accidental Discharge

Dear Dan,

We were sorry to learn of the unfortunate incident that you experienced while using your Remington Model 700 rifle. Thankfully no one was injured and your truck was only wounded. As we discussed, send me an estimate on replacing the windshield. No promises except that we will take it under consideration based on our findings from the gun examination.

I have enclosed an ARS label for you to return the incident rifle to my attention. We have agreed to clean the action and install a new trigger assembly under our bolt lock modification program. We have also agreed to wave the normal charges for this service. Please put a copy of this letter in the shipping box – add your telephone number, and a brief description of the incident. The note inside the box is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly.

We apologize for the inconvenience that this incident has caused; but, hope that our actions will keep you as a loyal Remington customer. If you have any questions feel free to contact me directly.

Sincerely,

Supry

Fred Supry, Manager Product Service and Law Enforcement Training Remington Arms Company 14 Hoefler Avenue Ilion, NY 13357

Phone: 315-895-3606 E-mail: fred.supry@remington.com

> Remington Arms Company, Inc. • 14 Hoefler Avenue • Ilion, NY 13357 Phone 315-895-3200 • www.remington.com

UPS DRIVER INSTRUCTIONS:	YOU ARE AUTHORIZED TO A	CCEPT THIS PACKAGE WITHOUT A	PICKUP RECORD.
Name: DAN	Klessig		
Company:	······································	,	
street: 5508 Boot Log Road			
City: Eagle R	iver	State: WI	54521
	REF #		
F	TO: FRED	supry	
A.R.S.	S REMINGTON ARMS		
	14 HOEFLER		
PD	ILION	<u>NY 13357</u>	
UPS 3 Day Select <sup>™</sup>			
TRACKING NUMBER			
1Z E13 390 57 5000 1796			
DAY SELECT AUTHORIZED		IEF #/DATE	

Ę

1