

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO. D916767		COMMENTS			
DATE RECEIVED 12/06/96	DATE OPENED 12/12/96	DATE CODE PD 6-83	SERIAL NUMBER 06468048	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-32401	
ACCESSORIES H/STUDS							

FROM: K MART ENTERPRISES P.O. BOX 3150 TROY MI 48064	SHIP TO: K MART 4166-80 5956 CENTRAL AVE W TOLEDO OH 43616
--	--

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	FROM DATE	ESTIMATED 1-2-97	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	----------------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED
CUSTOMER'S REQUEST	<i>Gun fires when safety is taken off</i>				

MAIN FAULT	<i>No fault found - trigger and safety assembly operate normally. Trigger pull 4#; can't off 1012. Cannot duplicate complaint. However, trigger assembly is contaminated with sticky residue. Bolt stop is sticking to receiver and moving freely. The sticky residue with cold temperatures could cause problem.</i>
------------	---

PARTS	<i>Sent gun to clean parent trigger assembly (if possible) or, we can install a new trigger assembly. Normal cost as a gesture of good will. It will better restore confidence in the rifle.</i>
-------	--

REPAIRMAN RRS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

SHOPS INC. 1/96