

DX # 9/73

May 20 - 2002

Remington Arms

Dear Sir.

47467

It has been brought to my attention to send my Model 700 - 7mm magnum - to the factory for modification as outlined in BUGLE magazine April 002 issue. The bolt on my Rifle will not open while the safety is on.

My rifle has fired on 4 occasions by merely taking the safety off and not touching the trigger while elk hunting. You can imagine my surprise! I took it to a gunsmith who thought it may just need a good cleaning as he could not figure out the inadvertent firing. Thank you. Sincerely. Ed Laurener