

# Remington.

## Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700	Serial Number: 6441674
Name: CHARLES LOAN	Date of Purchase: SEP 1989 USED
Address (no PO Boxes):	
14 UTAH TRAIL	
City: MEDFORD	State: NJ Zip: 08055
Phone (Daytime): 609-654-9286	Fax: 609-953-2797
E-mail Address:	

Please describe your problem:

- ① RIFLE DISCHARGED (FIRED) WHEN SAFETY WAS MOVED FROM SAFE TO FIRE
- ② BL SAFETY PROGRAM

Addition: (Please include headload specifications, etc.)

Serial Number:

6441674

Model: 700

NOTE: Please estimate

① WARNING: FEDERAL (WITH ZIP)



RE00049627

is provided and

THIS IS A VIOLATION OF AND INCLUDE NAME, ADDRESS

- Record
- Pack y
- ship in a firearm box.
- Remove all accessories from your firearm to prevent loss.
- Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Pat  
Coke  
LU  
2/71

7/29/02 1007 4006/4015

Custom duty, mag unity,

Ref. Service center

Replacing crown \$20.00

<http://www.remington.com/support/repairsvc/repairform.htm>

Quote

#49627

4/14/02

PS03799