

File Number:	17710		Arms Service number:	47921	
Last Name:	LOHT		First Name:	SHARON	
Street:	404 BOYD STREET		City:	GOLPEN	
State:	GO	Zip:	80403	Home Ph:	303-279-8940
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1025	
Concern:	UNEXPLAINED DISCHARGE WHILE UNLOADING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	6/14/2002	Date Opened by P/S:	6/14/2002	Caliber:	3006
Date of Incident:		Date Closed:	6/14/2002	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	6258681	Date Code:	
RAMAC:	700	Date Mfgd:	4/3/1969		
Litigation:	☐	PreLitigation:	☐	Obsolete:	☐
Custody:		Comments:	Could not duplicate concern, Trigger assembly and underside of action coated with sticky residue, debris, and rust. Replace TA, clean action under bolt lock modification program. Repair and shipping documents 7/10/02		
Time of Modification:	1:06:01 PM				
Date of Modification:	6/14/2002				