

File Number:	17674		Arms Service number:	47668	
Last Name:	LOWE		First Name:	JAMES T.	
Street:	5295 RICHARD DRIVE		City:	BEAUMONT	
State:	TX	Zip:	77708-1921	Home Ph:	409-892-4567
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1025	
Concern:	UNEXPLAINED DISCHARGE				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	QUOTE - BLM PROGRAM			Settlement Amount:	\$0.00
Date Opened Rem:	6/4/2002	Date Opened by P/S:	6/5/2002	Caliber:	3006
Date of Incident:		Date Closed:	6/5/2002	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	6291321	Date Code:	RS
RAMAC:	700	Date Mfgd:	11/20/1969		
		Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
		Obsolete:	<input type="checkbox"/>		
Custody:		Comments:	Could not duplicate concern. Altered settings on TA, TA coated with sticky residue, Bolt release sluggish due to residue. Quote \$20 for cleaning action and new TA under bolt lock modification program. Repair and shipping documents 6/14/02		
Time of Modification:	8:44:42 AM				
Date of Modification:	6/5/2002				

PS03811