

REMINGTON ARMS CO.
CUSTOMER SERVICE DIVISION
ILION, NY

I am returning one of your Remington model 700 ADL rifle in 25/06 caliber. The serial number is 6337799. I need to have the sear either replaced or repaired as the rifle will now sometimes fire upon releasing the safety. I have heard of similar stories on older model 700's & would like to know if this problem is covered by the warranty & if it can be corrected permanently. Please contact me at the phone number or address shown below. Thank you.

316-421-5674
501 SOUTH WASHINGTON
ALTAMONT, KS 67330

CHRIS M. LAHEY

Chris M. Lahey