August 14, 1995

Remington Arms Company, Inc. 14 Hoesler Avenue Ilion, NY 13357

Attn: Repair Division

Gentlemen:

This rifle belongs to my son-in-law in Alaska. I would like to get it repaired for him. It has inadvertently fired twice without pulling the trigger. I talked to a gun dealer and find that was a recall problem with this Remington, Model 700, Ser. # 6572059.

I called your company and was told to send it to you for repair.

If you have any questions, please phone me at 301-825-2868.

Thank you.

Sincerely,

Joseph L. White 1863 Cliff's Place Layton, UT 84041

Owner of this rifle is: Sgt. Gerald L. Lautenschlager of 1863 Cliff's Pl. Layton, UT 84041

,,