

RECEIVING AND ESTIMATING REPORT

COMMENTS

*To Product Service*ORDER
R 95-03351

INITIAL FFB	CUSTOMER ORDER NO. 2160				
DATE RECEIVED 01/16/95	DATE OPENED 01/26/95	DATE CODE EB 10-81	SERIAL NUMBER B6350348	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06 LM/BDL
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT			

FROM: LONGACRES
358 CHESTNUT ST
ABILENE TX 79602

SHIP TO: LONGACRES
358 CHESTNUT ST
ABILENE TX 79602

CUST NO:006401 ILIIONL

ACCOUNT NUMBER 003103	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 2-28	VIA UPS
GUN CONDITION ☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED		<i>See engagement was beyond window in housing (excessive)</i> <i>3/2</i>			REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL <i>2800</i>

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.				D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Mfr. 10/81 Unable to duplicate customers concern as recd. Trigger Assy has been adjusted outside of factory and sear and trigger were gummed up with old solidified oil. Exchange trigger Assy. at a special price strictly as a gesture of good will.*

PARTS <i>Trig. Assy.</i>	COMMENTS <i>Trigger pull measured 4 LBS as recd. Sear lift was .014</i> <i>Replace stock washers with adhesive backed spacers</i> <i>See owners manual for proper care and maintenance</i>				
REPAIRMAN <i>BSA</i>	PROOF	CLEAN ☒	TEST ☒	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS04004