

RECEIVING AND ESTIMATING REPORT

INITIAL **FPS** CUSTOMER ORDER NO. **94-15230**

DATE RECEIVED **05/06/94** DATE OPENED **05/09/94** DATE CODE **PH 6-87** SERIAL NUMBER **B6837357** NEW SERIAL NUMBER MODEL AND GRADE **700 30-06 ADL**

ACCESSORIES **W7STUDS** **L/REAR SIGHT**

FROM: **MENZIES, SCOTT
8 MANOR PLACE
HUNTINGTON STATION** SHIP TO: **MENZIES, SCOTT
8 MANOR PLACE
HUNTINGTON STATION**

NY117-46 **NY117-46**

CUST NO: **097052 D.O.D**

ACCOUNT NUMBER ACCOUNT NUMBER NC FROM DATE ESTIMATED VIA **UPS**

GUN CONDITION
☐ NEW
☐ SLIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE **20.00**
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3				
BARREL ASSY.		B5				
REC. ASSY.			D2		E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Upon receipt bolt group and barrel had due to unit in bottom firing pin
 threads. Could not disassemble barrel, firing pin the set was removed. Examination did
 not find on barrel, action, and trigger assembly. Saw magazine cover, but then it was
 with magazine from back of magazine.*

PARTS *Mag Full - 5.2 lbs. Barrel ft. on* COMMENTS *Rebar exports trigger assembly,
 #26345 trigger assembly. Both when action set 1/2 moved up and
 cost in price of good used.*

REPAIRMAN **T.D.L.** PROOF ☒ CLEAN ☒ TEST ☒ TARGET ☒ PATTERN

GALLERY TESTER DATE DATE DATE DATE DATE DATE

OFFICE COPY RO6925 REV. 1/94

to A/S 5/19/94