

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-06182

CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/19/92

02/27/92

ED 10-83

B6502403

700 25-06

BDL

ACCESSORIES

W/STUDS

L/REAR SIGHT

FROM:

MORRISON, NORMAN E
BOX 124
WILLIAMSTOWN

VT 05679

SHIP TO:

MORRISON, NORMAN E
BOX 124
WILLIAMSTOWNVT
05679

CUST NO: 058777 CJO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

3-20-92

UPS

GUN CONDITION:

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Cannot duplicate complaint - trigger and safety assembly
operates properly in every respect.

Trigger pull 4 1/2 pounds; rear left .012"

PARTS

COMMENTS

Offer to return rifle as-is, or
to replace trigger assembly at
normal cost as a gesture of good will,
if that will better restore safety service
to the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91

PS04043