

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R92-17664INITIAL
FPS

CUSTOMER ORDER NO.

ATTN: JIM STEKL

DATE RECEIVED
08/24/92DATE OPENED
09/02/92DATE CODE
CZ 4-75SERIAL NUMBER
6855517

NEW SERIAL NUMBER

MODEL AND GRADE

700 270 WIN BDL

ACCESSORIES SLING STRAP W/STUDS

W/SWIVELS

SCOPE BASE

FROM:

MAIL BOXES ETC.
ROBERT HUMASON
5114 BALCONES WOODS DR.
AUSTIN TX 78759

SHIP TO:

MAIL BOXES ETC.
ROBERT HUMASON
5114 BALCONES WOODS DR.
AUSTIN TX 78759

CUST NO: 065806 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

fault not duplicate complaint. Rifle and trigger assembly operate normally. Inspection of the trigger assembly did reveal an excessive amount of oil, dust, etc. but this condition did not adversely affect operation of the assembly. Trigger pull 5 pounds; rear- lift .008"

PARTS

COMMENTS

Per phone call to customer, install new trigger assembly at 1/2 normal cost, as gesture of good-will.

New style - no bolt lock

Customer does not want returned C.O.D., send bill

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/82

PS04076