

Dear Sirs

Please Inspect & Repair This
Rifle I have Enclosed.

The Problem is That Occassionally
When the Firing Pin is Cocked
And The SAFETY is Turned
OFF it will Instantaneously
Fire (Very Dangerous). Also,
When the Bolt is pulled Back,
The Firing Pin Cocks, But
When the Bolt is Closed the Pin
1/4

Will also uncock. Again
This problem is occasional
I have owned this particular
Gun since the late 1970's
It has been defective
since 1985. I would
Really like this Gun to
Hunt with it again so I would
Really appreciate a speedy
& ~~thorough~~ Thorough Investigation
& Repair

2/4.

The Model is

Rem 700 BDL

22-250 CALIBER

S/R A6388181

Also would you please

tell me when the gun

was built and any Ball

info including Recommended

Bullet loads.

Thank you
Don Mc

3/4

Please Return This Rifle
To Either Address

Don McRae
c/o C.A.S. Iberia
5900 Cassandra Smith Rd.
Hixson TN 37343

OR

Don McRae
19 Lee Circle
Ft. Ogle GA 30742

4/4