

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00046001 Account # - R-	Description/Serial Number 223211 Model 722 Center Fire Caliber: 222	Date Received - 5/13/2002 Estimate Date - 5/8/2002 Current Date - 5/25/2002
Customer RUDY MRVOS 6062 MRVOPS RD HARTSTOWN. PA 16131 US Phone (H) (724)-932-3435 Phone (W)	Return To RUDY MRVOS 6062 MRVOPS RD HARTSTOWN. PA 16131 US Fax Email	

Problems			
Reported		Found	
M992	UNINTENTIONAL FIRINGS	M123	FORWARD TO PRODUCT SERVICE FO
		M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	could not duplicate, quote customer new tpa under bolt lock mod program

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104 -	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	22	

REMINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
MILTON NY 13357


10 LBS 1 OF 1

COD

SHIP

TO:

RUDY MRVOS
6062 MRVOPS RD
HARTSTOWN PA 16131




PA 163 1-01



UPS GROUND

TRACKING #: 1Z 114 813 72 1188 9692



BILLING: PREPAID
COD \$21.20

INV#: RE00046001

ASC 3.70 J69K/J64K 14.0 01/2002