

File Number:	15131	Arms Service number:	21860
Last Name:	MANZER	First Name:	MELVIN L.
Street:	BOX 335	City:	SOUTH GIBSON
State:	PA	Zip:	18842
		Home Ph:	
Work Ph:	717-222-4437	Product Type:	F F A T O
Type Concern:	S PI PD P S	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SUPRY	Classification:	UNJ UNJ UNC UND
Settlement Detail:	INSTALL NEW TA AT SPECIAL PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	2/2/01	Date Opened by P/S:	2/2/01
		Caliber:	8MM
Date of Incident:		Date Closed:	2/2/01
		Bullet Weight:	
Date to Analysis:		Date from Analysis:	
		Manufacturer:	
Model:	700	Serial:	A6472789
		Date Code:	PO
		Date Mfgd:	6/27/77
RAMAC:	700	Litigation:	<input type="checkbox"/>
		PreLitigation:	<input type="checkbox"/>
		Obsolete:	<input type="checkbox"/>
Custody:		Comments:	Could duplicate FSR by pulling trigger with safe on then moving the safety to the ready to fire position - Outside of TA and action recently cleaned - Inside the TA was so sticky that the trigger and bolt release could barely move.
Time of Modification:	11:46:54 AM		
Date of Modification:	2/2/01		