

PRODUCT 200-2

D

**REPAIR
TAG**

776461

W. JOHNSON SERVICE INC.
Spring Cols - Cincinnati
3554 N. Algonquin
ADRIAN, MICHIGAN 49221
(517) 255-2545

CUSTOMER <u>TOMMY PAUL POULOS</u>		COPY NO. D 776461	
ADDRESS <u>1085 HERITAGE</u>		PHONE <u>734-429-5937</u>	DATE RECEIVED <u>12-30-02</u>
MODEL OR SERIAL NO. <u>SALINE MI 48178</u>	TROUBLE REPORTED <u>429-5937</u>		
DESCRIPTION OF MATERIAL USED		AMOUNT	
<u>IMPACT TRIGGER ASSEMBLY</u>			
<u>trigger assembly inspection not required by warranty</u>			
<u>(WARRANTY) Scope Screw broken</u>		TOTAL MATERIALS	LABOR <u>10</u>
RECEIVED BY <u>Thank You! CASH</u>		TAX	TOTAL
ON COMPLETION OF WORK →			

PRODUCT 200-2

D

**REPAIR
TAG**

776463

W. JOHNSON SERVICE INC.
Spring Cols - Cincinnati
3554 N. Algonquin
ADRIAN, MICHIGAN 49221
(517) 255-2545

CUSTOMER <u>James Mistopoulos</u>		COPY NO. D 776463	
ADDRESS <u>1085 Heritage</u>		PHONE <u>734-429-5937</u>	DATE RECEIVED <u>12-30-02</u>
MODEL OR SERIAL NO. <u>Saline MI</u>	TROUBLE REPORTED		
DESCRIPTION OF MATERIAL USED		AMOUNT	
<u>Clean up threads on Bolt Stop Screw</u>			
<u>fall Fines</u>			
<u>(WARRANTY) readjust trigger seal broken on weight of pull</u>		TOTAL MATERIALS	LABOR <u>20</u>
RECEIVED BY <u>screw and screw was backed out</u>		TAX	TOTAL
ON COMPLETION OF WORK →			