

RECEIVING AND ESTIMATING REPORT

INITIAL LCS		CUSTOMER ORDER NO.		COMMENTS	
DATE RECEIVED 12/06/90	DATE OPENED 12/11/90	DATE CODE AM 3-65	SERIAL NUMBER 134230	MODEL AND GRADE 700 30-06 ADL	ORDER R 90-32245
ACCESSORIES					

FROM: **MCCRARY, JERRY**
PO BOX 235
KODIAK AK 99615

SHIP TO: **MCCRARY, JERRY**
PO BOX 235
KODIAK AK 99615

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA V351110213
----------------	--------------------	--	------------	-----------	--------------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☒ VERY WORN ☒ MISUSED ☒ MARRED

CUSTOMER'S REQUEST: *It has been occasionally firing prematurely as the safety is pushed forward or the bolt is forward to the cocked position.*

MAIN FAULT: *Trigger assembly contaminated with gummy residue and rusting; internal parts not moving freely.*

PARTS	<i>Send repair quotation for 1/2 normal price on replacement bolt-look safety trigger assembly. Gun is 25 years old.</i>					
	REPAIRMAN JTB	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE