

RECEIVING AND ESTIMATING REPORT

COMMENTS

potter

ORDER
R 93-16020

TIAL	CUSTOMER ORDER NO.		DATE RECEIVED		DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
10M			07/26/93	07/29/93	PI 6-76		A6313708		700 308	ADL
ACCESSORIES			W/STUDS							

DM:	SHIP TO:	
<i>Set up full</i> MEDLIN, BILL 1056 HONEYCREEK RD CONYERS GA 30208		MEDLIN, BILL 1056 HONEYCREEK RD CONYERS GA 30208

CUST NO: 081500 C.J.D.L

COUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
			8-18-93	UPS
CONDITION			REPAIR CHARGE	
NEW			EXCISE	
LIGHTLY WORN			TAX	
WORN			INSURANCE	
VERY WORN			UPS	
UNREPAIRABLE			PARCEL POST	
MARRED			TOTAL	

STOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
3GER GROUP		B2			E1	F1
T ASSY.		B3			E2	F2
REL ASSY.		B4			E3	F3
C. ASSY.		B5			E4	F4
OD			C1	D3	E5	F5
AL			C2			

FAULT

Upon receipt, unable to duplicate customer concern.

upper part - 3 lbs. Rifle in good condition for 1976 mfg. Study was made for action.

lower part - .009

When taking safety off

Mr. Potter stated that one of our Warranty Dept. attempted to repair by replacing. Examination does not indicate any tampering or malfunction.

Agreed to replace component trigger assembly with new style & return action as given by customer good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>R.B.S.</i>		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS04403