

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00074871	Description/Serial Number ML016204	Repairman - Herb Brown
Account # - R-	Model 700ML Center Fire with 24 inch barrel Caliber: 50 VSCOPE BASE	Date Received - 1/5/2004
Customer MICHAEL MARSHALL 1571 CAREY PLACE FREDERICK, MD 21701 US		Estimate Date - Current Date - 1/6/2004
Phone (H) (301)-694-8516 Phone (W) (443)-310-9432 Xcell		Return To MICHAEL MARSHALL 1571 CAREY PLACE FREDERICK, MD 21701 US
	Fax	Email

Reported	Problem	Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M992	FIRES WHEN TAKEN OFF SAFE		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F99294	700 ML SS TRIG ASSB	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:		1	1	0	

Problem/Notes Could not duplicate customers concern. Altered adjustments and excessive oil. Install new trigger assm. n/c.					
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date