

PS

Mill Creek Sport Center  
8180 Main St.  
Dexter MI 48130  
734-426-3445  
millcreek@att.net

February 26, 2002

Remington Arms Co.  
Warranty Service  
14 Hoefler Ave.  
Ilion, NY 13357

*Date Code*  
*wj 8/62*

Warranty Service,

Enclosed is a Remington 700 30-06 Rifle ser# 26141. It is being sent in for factory warranty service. The rifle has fired when the safety was turned off. Please replace the trigger/ safety assembly. This should be a warranty repair even though the gun is out of warranty. If you need additional information please contact me Tues through Fri 11 am to 7 pm.

Serial Number: **26141**

Thank you

Model: **700**

*Maureen Cross*  
Maureen Cross, A



**RE00042888**

*3/8/02*

*Action & trigger assembly covered with sticky substance.  
Rifle poorly maintained. Bolt stop release says up.*

*1962*

*Clean action & replace trigger assembly 20.00 plus 54H  
90 thread*