

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 92-04497

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

01/31/92

DATE OPENED

02/06/92

DATE CODE

0D 7-83

SERIAL NUMBER

B6481095

NEW SERIAL NUMBER

MODEL AND GRADE

700 243

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

NORTHERN IOWA SPORTS SUPPLY  
NORTHERN IOWA SPORT SHOP  
12 7TH AVE SE  
WAUKON IA 52172

SHIP TO:

NORTHERN IOWA SPORTS SUPPLY  
NORTHERN IOWA SPORT SHOP  
12 7TH AVE SE  
WAUKON IA 52172

CUST NO: 00B491 IWION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Trigger assembly has been improperly adjusted outside factory  
1.) trigger pull measured at 2# - well below our minimum spec. (2) insufficient over travel; 3.) excessive rear engagement. In addition to the above, the extremely light trigger pull resulted in improper operation of the trigger spring - the trigger does not re-set upon cocking. Trigger assembly not operating properly as received.  
Trigger pull 2 pounds; rear-set - 0.11"

PARTS

COMMENTS

Offer replacement trigger and at a reduced cost, as a gesture of good will. Since rear engagement has been improperly altered outside factory, we cannot re-adjust in service.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTE

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV

PS04473