

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00054526	Description/Serial Number 118303	Date Received - 10/24/2002
Account # - R-	Model 660 Center Fire Caliber: 6 MM	Estimate Date - Current Date - 10/28/2002
Customer NIAGARA OUTDOORS 223 WITMER RD NORTH TONAWANDA, NY 14120 US	Return To NIAGARA OUTDOORS 223 WITMER RD NORTH TONAWANDA, NY 14120 US	
Phone (H) (716)-570-7122 Xcell Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M993	FORWARD TO PRODUCT SERVICE FO
M176	RETURNED FOR RECALL/UPDATE		
M238	CLEAN & INSPECT		

Technician's Comments	
ProblemNotes	Trigger assembly settings out of adjustment, trigger will not reliably return under sear. Never updated. Update per current produres per FLS.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F91469	600 TRIGGER ASSB	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		2	