

Repair Order Number



|                                                                        |                                               |                                                                         |
|------------------------------------------------------------------------|-----------------------------------------------|-------------------------------------------------------------------------|
| Repair Order Number<br>RE00049939                                      | Description/Serial Number<br>6430819          | Repairman - Robert Frink<br>Date Received - 8/20/2002                   |
| Account # - R-                                                         | Model 600 MOHAWK Center Fire<br>Caliber: 6 MM | Estimate Date - 8/5/2002<br>Current Date - 9/12/2002                    |
| Customer<br>ERIC NUSE<br>657 MAPLE HILL RD<br><br>JOHNSON. VT 05656 US |                                               | Return To<br>ERIC NUSE<br>657 MAPLE HILL RD<br><br>JOHNSON. VT 05656 US |
| Phone (H) (802)-241-3723<br>Phone (W)                                  |                                               | Fax<br>Email                                                            |

| Reported |                                              | Found |                              |
|----------|----------------------------------------------|-------|------------------------------|
| M123     | FORWARD TO PRODUCT SERVICE<br>FOR INSPECTION | M123  | FORWARD TO PRODUCT SERVICE F |
| M992     | DISCHARGED WHEN SAFETY<br>PUSHED OFF         | M176  | RETURNED FOR RECALL/UPDATE   |

| Material #     |  | MaterialDesc                  | Quantity<br>Needed | Quantity<br>From Inv | Quantity<br>From Kit | Warranty<br>(Y/N) |
|----------------|--|-------------------------------|--------------------|----------------------|----------------------|-------------------|
| Part           |  |                               |                    |                      |                      |                   |
| F91469         |  | 600 TRIGGER ASSB              | 1                  | 1                    | 0                    | Y                 |
| Part Total:    |  |                               | 1                  | 1                    | 0                    |                   |
| Service        |  |                               |                    |                      |                      |                   |
| 4000104        |  | ARMS SERV SHIPPING & HANDLING | 0                  | 0                    | 0                    | Y                 |
| 4000119        |  | GR-TEST                       | 1                  | 1                    | 0                    | Y                 |
| Service Total: |  |                               | 1                  | 1                    | 0                    |                   |

|                |                                                                         |       |      |        |         |
|----------------|-------------------------------------------------------------------------|-------|------|--------|---------|
| ProblemNotes   | Could not duplicate concern. Install new trigger assembly. FLS 8/02/02. |       |      |        |         |
| Repairman      | Proof                                                                   | Clean | Test | Target | Pattern |
| Gallery Tester | Date                                                                    | Date  | Date | Date   | Date    |


9 LBS 1 OF 1

REMINGTON ARMS CO INC  
800 243-9700  
14 HOFER AVE  
ILION NY 13357

SHIP

TO:

ERIC NUSE  
657 MAPLE HILL RD  
JOHNSON VT 05656




VT 056 0-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1194 1727



BILLING: P/P

INV#: RE00049939

ASC 05.00 J69K/J64K 16.0A 01/2002