

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047154 Account # - R-	Description/Serial Number 218277 Model 721 Center Fire Caliber: 270	Date Received - 6/13/2002 Estimate Date - 6/3/2002 Current Date - 7/15/2002
Customer HAROLD NORRIS 41130 STATE ROUTE 558 LEETONIA, OH 44431 US	Return To HAROLD NORRIS 41130 STATE ROUTE 558 LEETONIA, OH 44431 US	
Phone (H) (330)-482-2580 Phone (W)	Fax Email	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M238	CLEAN & INSPECT	M238	CLEAN & INSPECT
M238	CLEAN & INSPECT	M239	REPLACE TRIGGER ASSEMBLY		

Technician's Comments	
ProblemNotes	action and trigger assm. covered with a heavy sticky substance poorly maintained replace trigger assm 20.00 dollars clean and inspect

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	22	


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

HAROLD NORRIS
41130 STATE ROUTE 558
LEETONIA OH 44431




OH 445 1-99



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 9110



BILLING: P/P

INV#: RE00047154

ASC 05.00 J69K/J64K 16.0A 01/2002