

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 721		Serial Number: 218277	
Name: HAROLD D. NORRIS		Date of Purchase: 1959?	
Address (no PO Boxes):: 41130 STATE ROUTE 558			
City: LECTONIA		State: OHIO	Zip: 44431
Phone (Daytime): 330 482 2580		Fax:	
E-mail Address:			
Please describe your problem:			
SAFETY RECALL			
RIFLE WAS DISCHARGED WHEN SAFETY WAS MOVED FROM "SAFE" TO "FIRE" POSITION			
Additional Information: (Ammo type, brand, handload specifications, etc.)			

*Date Code
PN
6/51*

47154



Serial Number: **218277**
Model: 721



Contact the Repair Center for services

FOR FIREARM OR IN THE SAME BOX WITH THE FIREARM. MUST SEND SPENT SHELLS PLEASE SEND THEM IN A ZIP CODE), TELEPHONE AND MODEL AND SERIAL

- Remove all accessories from your firearm.
- Remove all spent shells from your firearm.
- Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

5/30/02 Action & trigger assembly. Covered with a heavy sticky substance. Poorly maintained. Replace trigger assembly \$2000. Quote 1007 4015

<http://www.remington.com/support/repairsvc/repairform.htm>

3/27/2002