

TAL CUSTOMER ORDER NO.					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/93	04/14/93	XU 12-71	6501534		700 22-250 BDL
CATEGORIES		SCOPE BASE			
W/STUDS		L/REAR SIGHT			

FROM:	SHIP TO:
<i>Set up full</i> NORTHWESTERN INDUSTRIES 416 W MAIN LEON A PYTLIK VALLEY CITY ND 58072	NORTHWESTERN INDUSTRIES 416 W MAIN LEON A PYTLIK VALLEY CITY ND 58072

COUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED	VIA
			4/29/93	UPS
CONDITION	REPAIR CHARGE			
NEW	EXCISE			25.00
SLIGHTLY WORN	TAX			
MORE WORN	INSURANCE			
VERY WORN	UPS			
UNREPAIRABLE	PARCEL POST			
DAMAGED	TOTAL			

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
TRIGGER GROUP		B2			E1	F1
TRIGGER ASSY.		B3		D1	E2	F2
REL ASSY.		B4		D2	E3	F3
ASSY.		B5		D3	E4	F4
MOD			C1		E5	F5
AL			C2			

Upon receipt of the rifle is inspected. Finding per following concerns
 it is found. Examination reveals that all 3 trigger adjustment screws
 have been tampered with within the factory. No contact on adjustment
 screws, all contact found on rear adjustment screw.

COMMENTS	
Replaces trigger assembly completely and then action at 1/2 normal replacement cost at price of gun will.	
REPAIRMAN	PROOF
JTB	
GALLERY TESTER	DATE