

Repair Order Number



Repair Order Number RE00086988	Description/Serial Number G6279759	Repairman - Richard Hults Date Received - 10/26/2004
Account # - R-	Model 700 Center Fire with 24 inch barrel Caliber: 300 REM SA UMAG BDL	Estimate Date - Current Date - 11/1/2004
Customer NEW ERA SHOOTERS SUPPLY 1745 GRAYSON TURNPIKE WYTHEVILLE, VA 24382 US	Return To NEW ERA SHOOTERS SUPPLY 1745 GRAYSON TURNPIKE WYTHEVILLE, VA 24382 US	
Phone (H) (276)-228-4776 Phone (W)	Fax Email	

Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN TAKEN OFF SAFE		

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes could not duplicate trigger & trigger in rusted not allowing trigger to retrun to position replace trigger check over at n/c under warranty					
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date