

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-26548

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
12/13/91

DATE OPENED
12/18/91

DATE CODE
DE 9-84

SERIAL NUMBER
R6633886

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

ADL

ACCESSORIES

W/SWIVELS

SCOPE BASE

FROM:

ORANGE GROVE FIREARMS
P O BOX 301
ORANGE GROVE
USA

TX 78372

SHIP TO:

ORANGE GROVE FIREARMS
P O BOX 301
ORANGE GROVE
USA

TX
78372

CUST NO: 054944 C.B.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

"Gun feeds when bolt is locked down - accidental misfire"

MAIN FAULT

As received, bolt would not rock at all. Disassembly of rifle reveals inside of trigger assembly is contaminated with gunning substance. Semi-safety clip was sticking to side plate of trigger assembly. Both of action and outside of trigger assembly very dirty. Bolt does not operate properly because of gunning substance on surface.

PARTS

COMMENTS

*1) Offer new trigger assembly at 1/2 normal cost, as gesture of good-will
2) clean up bottom of barrel of receiver*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 8/9

PS04616