306 Brookwood Drive Duncanville, TX 75116

August 30, 1994

Remington Arms Company 14 Hoesler Avenue Ilion, New York 13357

Attention: Arms Service Division

This Remington Model 700, Serial Number 666 1073, is being returned to you for inspection and any revisions that are necessary to upgrade the gun to your current design and - non be

The gun has never been to a gunsmith for repairs. It has had relatively few rounds  $(200^{\pm})$  fired from it.

The gun has fired inadvertently when closing the bolt and ./ when the safety was released. Fortunately, no one was in- jured as a result of these misfires.

please make the necessary changes as soon as possible and submit the bill to me at the above address. If you have questions or comments, please call me at 214 298 1025.