

Could not duplicate
Concern.

Heavy oil in TA
Install new TA at
1/2 normal price.

FLS 6/12/01

Number: **A6663941**

Model: **700**



RE00028368

The customer said, when
closing the Bolt on this
Rifle, In cold Temperature
the firing Pin follows.
Please repair.

Thanks Ken

Number:

A6663941

Model: 700



RE00028368

The Customer said, when
closing the Bolt on this
Rifle, In cold Temperature
the firing Pin follows.
Please repair.



Thanks

Ken