

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00046441 Account # - R-	Description/Serial Number C6490558 Model 700 Center Fire Caliber: 22250 ADL	Date Received - 6/3/2002 Estimate Date - 5/22/2002 Current Date - 6/11/2002
Customer POTEAU PAWN & GUN SHOP INC 407 NORTH BROADWAY POTEAU, OK 74953 US	Return To POTEAU PAWN & GUN SHOP INC 407 NORTH BROADWAY POTEAU, OK 74953 US	
Phone (H) Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M990	FIRE WHEN TAKEN OFF SAFE	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
Condition	REC'D W/ WOOD DINGS.
Problem/Notes	fired when taken off safe. action and trig. assm covered with a sticky solution and rust rifly has not been cleaned properly in some time clean action replace trig at 20.00 dollars

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		22	

PS04770


10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

POTEAU PAWN & GUN SHOP INC
407 NORTH BROADWAY
POTEAU OK 74953




OK 749 2-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 4547



BILLING: PREPAID

INV#: RE00046441

ASC 3.70 J69X/J64X 14.0 01/2002